

DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Michael O. Leavitt Governor

Kathleen Clarke **Executive Director**

Lowell P. Braxton Division Director

1594 West North Temple, Suite 1210 PO Box 145801

Salt Lake City, Utah 84114-5801

801-538-5340

801-359-3940 (Fax)

801-538-7223 (TDD)

Partial: XXX Complete: Exploration:

Inspection Date & Time: <u>6/13/2000 / 10:00a.m.-2:00</u>p.m.

Date of Last Inspection: <u>5/23/2000</u>

Mine Name: <u>Dugout Canyon</u> County: <u>Carbon</u> Permit Number: <u>ACT/007/039</u>						
Permittee and/or Operator's Name: Canyon Fuel Company						
Business Address: P.O. Box 1029, Wellington, Utah 84542						
Type of Mining Activity: Underground XXX Surface Prep. Plant Other						
Company Official(s): Gary Taylor						
State Officials(s): Steve Demczak Federal Official(s): None						
Weather Conditions: Warm, 80's						
Existing Acreage: Permitted-4035 Disturbed-20.1 Regraded- Seeded- Bonded-						
Increased/Decreased: Permitted Disturbed Regraded Seeded Bonded						
Status:Exploration/_XXX_Active/_ Inactive/_ Temporary Cessation/_ Bond Forfeiture						
Reclamation (_Phase I/_Phase II/_Final Bond Release/_LiabilityYear)						
REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS						
Instructions						

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUAT	ED N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[XX]		[XX]	
2.	SIGNS AND MARKERS	XX	口	[XX]	$\overline{\square}$
3.	TOPSOIL	XX	\Box	$\overline{[XX]}$	ĪĪ
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[XX]	\Box	[XX]	\Box
b.	SEDIMENT PONDS AND IMPOUNDMENTS	XX		[XX]	\Box
c.	OTHER SEDIMENT CONTROL MEASURES		\Box	\Box	\Box
d.	WATER MONITORING	\Box	\Box		\Box
e.	EFFLUENT LIMITATIONS	$\overline{\square}$			\Box
5.	EXPLOSIVES	\Box	\Box		
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	\Box	\Box		\Box
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[XX]	\Box	[XX]	\Box
8.	NONCOAL WASTE	[XX]	\Box	[XX]	\Box
9.	PROTECTION OF FISH, WILDLIFE AND				
	RELATED ENVIRONMENTAL VALUES	\Box	\Box		
10.	SLIDES AND OTHER DAMAGE	\Box		\Box	\Box
11.	CONTEMPORANEOUS RECLAMATION				\Box
12.	BACKFILLING AND GRADING		\Box		
13.	REVEGETATION				\Box
14.	SUBSIDENCE CONTROL				\Box
15.	CESSATION OF OPERATIONS				\Box
16.	ROADS:				
	CONSTRUCTION/MAINTENANCE/SURFACING		\Box	\Box	\Box
b.	DRAINAGE CONTROLS		\Box	\Box	\Box
17.	OTHER TRANSPORTATION FACILITIES		\Box		\Box
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[XX]	\Box	[XX]	
19.	AVS CHECK (4th Quarter-April, May, June)(date)				
20.	AIR QUALITY PERMIT		\Box		\Box
21.	BONDING & INSURANCE	[]	[]	[]	[]

INSPECTION REPORT

(Continuation sheet)

Page <u>2</u> of <u>2</u>

PERMIT NUMBER: ACT/007/039

DATE OF INSPECTION: 6/13/2000

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMIT-

No amendments are submitted to the Division at this time.

2. SIGNS AND MARKERS -

Identification signs meet the requirements of the R645 Coal Rules. The perimeter markers were spot-checked and are located around the perimeter of the disturbed areas.

3. TOPSOIL PILE -

The topsoil for Dugout mine is being stored at the topsoil site at Soldier Creek Mine. It is separated from the topsoil of Soldier Creek Mine. Grass is beginning to grow on the topsoil pile.

4A. DIVERSIONS -

The diversions were functioning as designed. The majority of the diversions are concrete lined.

4B. SEDIMENT PONDS -

The sediment pond was functioning as designed. The sediment pond does contain water but will not likely discharge in the near future. No hazardous conditions were noticed during the inspection.

7. REFUSE -

There was no refuse being stacked or stored at Dugout mine. The permittee plans to submit an amendment for a refuse pile area.

8. NON-COAL WASTE -

The area was clear of non-coal waste material.

18. SUPPORT FACILITIES -

No new surface facilities have been built since the last inspection.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Chris Hansen (Canyon Fuel) Henry Austin (OSM)
Given to: Pam Grubaugh-Littig (DOGM) Filed to: Price Field Office

Date: June 26, 2000

Inspector's Signature: #39